



## Repairs to the Panthera X

As a result of our continued development of the Panthera X, we are pleased to present a list of different types of repairs for the carbon fibre frame.

We can now offer users a very affordable option for repairing frames that unfortunately have been spoiled by unsightly scratches, dents, vandalism or other damage.

The frame is sent to Panthera and, instead of replacing the entire frame with a new one, we replace, repair or refinish the damaged part.



- |   |                  |
|---|------------------|
| 1) Replacement of rear bar                | item no. 9910003 |
| 2) Replacement of rear upright            | item no. 9910004 |
| 3) Replacement of seat side               | item no. 9910001 |
| 4) Replacement of cross member            | item no. 9910002 |
| 5) Replacement of rear axle               | item no. 9910005 |
| 6) New refinish of frame or backrest      | item no. 9910007 |
| New refinish of frame <b>and</b> backrest | item no. 9910008 |
| 7) Dent/hole repair*                      | item no. 9910006 |

\* if possible. Repair of dent/hole damage is possible on the parts highlighted in illustration 8.