
pendhare.

Info sheet 2020-13 2020-10-05

Attention: Prescribers Technicians Purchasers

Bolt to inner casing castor fork X

Click on images for larger format



Bolt to inner casing castor fork on X

We have received comments from our customers that the bolt to the inner casing on the Panthera X castor fork can easily be damaged during service or repair. We therefor wish to make an improvement and replace this bolt with a new with a Torx T20 head. The function and mounting is the same but with a reduced risk of damage the bolt when loosing and tightening. We introduce this bolt when mounting on Panthera X wheelchairs and it is possible to order as a sparepart from 1st of October 2020. The price remains the same.

Present bolt:

Replacing bolt:

art.no. 6003408

art.no. 6003409DL